

Certificate

Inspection of the welding quality requirements according ISO 3834

Certificate no.: 01 240 E/A-20 4422.00

Name and address of the
certificate holder: **Manufacturas Vilassar, S.L. (MAIVISA)**
Pol. Ind. Vallmorena II
C/ Serra Vallmorena , 8-10
08339 Vilassar de Dalt (Barcelona)
Spain

It is hereby certified that the manufacturer has furnished
proof of the quality requirements according to the test basis.
The mentioned company:

- operates a quality system which ensures that the
manufacture and inspection of the products stated in our
report, are in compliance with applicable technical
standards and regulations;
- employs qualified supervisory and inspection personnel;
- has qualified welding processes and welding personnel;
- has adequate facilities permitting manufacture and inspection of
welded products.

Test basis: **EN ISO 3834-2**


Audit report no.: 92767812.10

Scope: **The scope of the inspection and other relevant data are
given in the annex to the certificate.**

Manufacturing plant: see certificate holder

Validity: **This certificate is valid until 2026-12-28.**

Cologne, 2024-01-03


Dipl.-Ing. Achim Makowka
Certification Body for welding manufacturers

TÜV Rheinland Industrie Service GmbH
Certification Body for welding manufacturers
Am Grauen Stein, D-51105 Cologne

M-012-Rev24